

Appendix 3: Llanberis to Beddgelert

Photos 43 & 49 – approx. 200m wet section and poached by livestock section just before Waunfawr. Grid Ref: SH 53143 59387



Photos 62 & 63 – Ladder stiles requiring anti-slip in woodland after Waunfawr. Around SH 52222 58511



Photo 101 Above Dorothea quarry before reaching Nantlle need for clearer waymarker so people don't go through kissing gate but instead keep to left of fencing.
At Grid Ref: SH 50371 54287. (nb, resolved already)



Photo 153 Bench examples - (bench on Rhyd Ddu to Beddgelert section, Grid Ref: SH 56603,52202) and 116 (bench in Nantlle, Grid Ref: SH 50932,53028).



Photo 65 – precarious ladder stile /railing northern edge of woodland out of Waunfawr which is exposed and tricky to use especially as at height in stone wall corner with drops either side - could do with safer structure over. SH52076 58385.



Photos 124 & 127 – long approx. 800m wet section east of Nantlle. Around centre point
Grid Ref: SH 51814,52804.



Photo 144 – Heritage style metal gate on route as Trail leaves Rhyd Ddu, Grid Ref: SH
57061,52579

