

Appendix 5: Llan Ffestiniog to Penmachno

Photo 13 – narrow slippery path in Ceunant Cynfal Nature Reserve just south east of Llan Ffestiniog. Grid Ref: SH 70796,40981



Photo 14 – fallen tree across route in Cwm Cynfal Nature Reserve south east of Llan Ffestiniog. Grid Ref: SH 70716,41030



Photo 22 – few fallen trees just before footbridge in the Cwm y Cynfal at western end.
Grid Ref: SH 72067,41041



Photo 39 – location by Llyn y Morwynion to north west of lake; stream could possibly do with small footbridge. Grid Ref: SH 73266,42264

